



**FIG. 1**  
**PRIOR ART**



**FIG. 3**



**FIG. 4**





FIG. 2A



4/5

W

H	W-8 ENABLED VALUES			00000000	SF=8
	00000000	W-8 ENABLED VALUES			
	W-12 ENABLED VALUES			000000000000	SF=4
	0000	W-12 ENABLED VALUES		00000000	
	00000000	W-12 ENABLED VALUES		0000	
	000000000000	W-12 ENABLED VALUES			
	W ENABLED VALUES				SF=16
	W ENABLED VALUES				SF=16
	W-8 ENABLED VALUES			00000000	SF=8
	00000000	W-8 ENABLED VALUES			
	W-12 ENABLED VALUES			000000000000	SF=4
	0000	W-12 ENABLED VALUES		00000000	
	00000000	W-12 ENABLED VALUES		0000	
	000000000000	W-12 ENABLED VALUES			
	W-8 ENABLED VALUES			00000000	SF=8
	00000000	W-8 ENABLED VALUES			

A<sup>H</sup> MATRIX

**FIG. 5**

H

W-15 ENABLED VALUES		0000000000000000
0	W-15 ENABLED VALUES	0000000000000000
00	W-15 ENABLED VALUES	0000000000000000
000	W-15 ENABLED VALUES	0000000000000000
0000	W-15 ENABLED VALUES	0000000000000000
00000	W-15 ENABLED VALUES	0000000000000000
000000	W-15 ENABLED VALUES	0000000000000000
0000000	W-15 ENABLED VALUES	0000000000000000
00000000	W-15 ENABLED VALUES	0000000000000000
000000000	W-15 ENABLED VALUES	0000000000000000
0000000000	W-15 ENABLED VALUES	0000000000000000
00000000000	W-15 ENABLED VALUES	0000000000000000
000000000000	W-15 ENABLED VALUES	0000000000000000
0000000000000	W-15 ENABLED VALUES	0000000000000000
00000000000000	W-15 ENABLED VALUES	0000000000000000
000000000000000	W-15 ENABLED VALUES	0000000000000000
0000000000000000	W-15 ENABLED VALUES	0000000000000000

21000  
 20000  
 19000  
 18000  
 17000  
 16000  
 15000  
 14000  
 13000  
 12000  
 11000  
 10000  
 9000  
 8000  
 7000  
 6000  
 5000  
 4000  
 3000  
 2000  
 1000  
 0

**FIG. 6**